


[1] PRODUCTION QUALITY ASSURANCE NOTIFICATION

[2] Equipment, Protective Systems or Components intended for use
in potentially explosive atmospheres
Directive 2014/34/EU

- [3] Notification Number: Nemko 13ATEX4087Q
- [4] Equipment, Protective System, or Components as listed: Profile Meter; Water Cut Meter.
 II 1/3/(1) G Ex ia; Ex e; Ex nA
- [5] Manufacturer: Sentech AS
Olaf Helsets vei 5G
N-0694 Oslo
NORWAY
- [6] Nemko Group AS, notified body number 0470 for Annex IV in accordance with Article 17 of Council Directive 2014/34/EU of 26 February 2014 notifies that the manufacturer has a production quality system which complies with Annex IV of the Directive.

This quality system in compliance with Annex IV of the Directive also meets the requirements of Annex VII, Conformity to type based on Product Quality Assurance.

- [7] This notification is based on audit report issued the 2022-02-10, related to order No. 456061, as well as corresponding corrective actions, if any.
Information about external factory site(s) covered by this QAN, if any, is given in audit reports related to the validity of this QAN.

The notification can be withdrawn if the manufacturer no longer satisfies the requirements of Annex IV.

Results of periodical surveillance of the quality system are a part of this notification.

- [8] This notification is valid until 2025-05-31 and can be withdrawn if the Manufacturer does not satisfy the production quality assurance surveillance / re-assessment.
- [9] According to Article 16(3) of the Directive 2014/34/EU the CE marking shall be followed by the identification Number 0470, identifying the notified body involved in the production control stage.

The full list of valid EU type examination certificates is maintained by the Notified Body.

This notification may only be reproduced in its entirety and without any change.

2022-02-24



Bernt Jonny Orderud
Manager factory inspections
Factory Inspection Department